

# IRC Congress 2016

## Proposals For 2017

### From Hellenic Offshore Committee

1.

Reason for change

During an Equipment Inspection, some dimensions may be found to exceed a maximum value or to be less than a minimum value, but at the same time they may lead to a non-significant change of the TCC. Furthermore, the difference of the measured dimensions may be caused by normal alterations during time or by measurement deviations, for which the owner is not responsible. However, according IRC Rule 8.10.3, in these cases the boat is not in compliance with her certificate, leading to penalty or disqualification.

Amend

If during Equipment Inspection any rated dimension is found to exceed a maximum value or to be less than a minimum value, the non-compliance of the boat with her certificate has to be in relation with the change in the TCC.

Effect of change:

No penalty should be applied if the TCC remains unchanged.